The **Heart** of the Engine's **Lubrication System**

CTP Oil Pumps

Quality Products

A worn out oil pump will cause a low oil pressure condition leading to serious engine damage, engine bearing failure, piston and liner seizure and critical parts wear and breakdown. CTP oil pumps are manufactured to strict ISO 9001 quality standards. Our engineers have extensive experience in designing engine components that adapt to specific conditions to prevent and cause engine wear. CTP oil pumps are manufactured to ensure unrivaled performance, reliability and longevity.

Part No.	Engine Model	Part No.	Engine Model
0676925	416	611346	3304, 3306
1003717	3056T	6N1030	992C, 3412
1068957	3306	6N2450	D9G, D9H
1068958	3306	6N2460	D353C
1161980	C27, C32, 3408E, 3412E	6N2642	33 06, D333C
1192925	3114	6N2790	955K
1614110	3408	6N2792	D5, D6, D6B/C, 922, 951B, 955H/K, 966, 977H/K
1614111	980C, 3406, 3406B	6N2793	D4C, D5
1614112	983B, 3406, 3406B	6N2809	12E, 12F, 14E
1614113	988B, 3408	6N2815	12E, 12F, 14E
1898777	3116, 3126, C7	6N2820	D5, D6C, D7F, 950, 955K
2P1784	3304, 3306, D333C	6N2821	D4D, D5, D6C, 920, 922B, 930, 941/B, 944, 951B
2P7830	12F, 14E, 120B, 3306, D6C	7C1531	657E, 773B
2004497	C7, 3116, 3126	7C1772	3412E, C27, C32
2168625	3056	7G3815	3306,
2335220	3176C, C12, C13	7N4170	D8, D8H, D8K
3318905	C9	7\$7602	3304
4N8735	3406, 3408	7\$9521	983, 988
5H1719	D8H, D8K	* Other part po	not included in the list are available. Please contact your sales

* Other part no. not included in the list are available. Please contact your sales representative if you have any questions.

Part Numbers are used for reference purposes only